

Table 1. Standard units

Unit	SI unit	Conversion factor	Conversion factor
mmHg	mmHg	1 mmHg = 133.322 Pa	1 mmHg = 1.36 × 10 ⁻³ m H ₂ O
cmHg	cmHg	1 cmHg = 1333.22 Pa	1 cmHg = 1.36 × 10 ⁻² m H ₂ O
mmH ₂ O	mmH ₂ O	1 mmH ₂ O = 9.80665 Pa	1 mmH ₂ O = 1 × 10 ⁻³ m H ₂ O
cmH ₂ O	cmH ₂ O	1 cmH ₂ O = 98.0665 Pa	1 cmH ₂ O = 1 × 10 ⁻² m H ₂ O
mH ₂ O	mH ₂ O	1 mH ₂ O = 9.80665 Pa	1 mH ₂ O = 1 × 10 ⁻¹ m H ₂ O
mmHg	mmHg	1 mmHg = 133.322 Pa	1 mmHg = 1.36 × 10 ⁻³ m H ₂ O
cmHg	cmHg	1 cmHg = 1333.22 Pa	1 cmHg = 1.36 × 10 ⁻² m H ₂ O
mmH ₂ O	mmH ₂ O	1 mmH ₂ O = 9.80665 Pa	1 mmH ₂ O = 1 × 10 ⁻³ m H ₂ O
cmH ₂ O	cmH ₂ O	1 cmH ₂ O = 98.0665 Pa	1 cmH ₂ O = 1 × 10 ⁻² m H ₂ O
mH ₂ O	mH ₂ O	1 mH ₂ O = 9.80665 Pa	1 mH ₂ O = 1 × 10 ⁻¹ m H ₂ O
mmHg	mmHg	1 mmHg = 133.322 Pa	1 mmHg = 1.36 × 10 ⁻³ m H ₂ O
cmHg	cmHg	1 cmHg = 1333.22 Pa	1 cmHg = 1.36 × 10 ⁻² m H ₂ O
mmH ₂ O	mmH ₂ O	1 mmH ₂ O = 9.80665 Pa	1 mmH ₂ O = 1 × 10 ⁻³ m H ₂ O
cmH ₂ O	cmH ₂ O	1 cmH ₂ O = 98.0665 Pa	1 cmH ₂ O = 1 × 10 ⁻² m H ₂ O
mH ₂ O	mH ₂ O	1 mH ₂ O = 9.80665 Pa	1 mH ₂ O = 1 × 10 ⁻¹ m H ₂ O